

# TECHNICAL BULLETIN



Subject:

## Clearance Specs for Airlocks

Bulletin #: **95277**      Rev: **E**      Created by: **MK**      Date: **2023-08-14**

ECR # **25099**      Production: X      Service: X      Sales: X  
 Product Lines: Transportation Equipment: X      Agri-vac/Pneumatic Equipment: X

Tables of airlock specifications can be found below.

### Airlock Specification

The following table lists the specifications of new airlocks manufactured by Walinga.

	TIP CASING TOP		TIP CASING BOT		ROTOR END-PLATE	
	Min	Max	Min	Max	Min	Max
<b>1008 DT</b>	0.003	0.006	N /A		0.004	0.006
<b>1210 DT</b>	0.004	0.007	N/A		0.005	0.007
<b>1314 DT</b>	0.004	0.007	N/A		0.005	0.007
<b>1314 BT</b>	0.005	0.007	0.004	0.007	0.005	0.007
<b>1618 DT</b>	0.004	0.007	N/A		0.007	0.009
<b>1618 BT</b>	0.006	0.008	0.004	0.008	0.007	0.009
<b>2018 BT</b>	0.008	0.010	0.005	0.010	0.007	0.009
<b>2224 DT</b>	0.006	0.010	N/A		0.010	0.013

# TECHNICAL BULLETIN



Subject:

## Clearance Specs for Airlocks

Bulletin #: **95277** Rev: **E** Created by: **MK** Date: **2023-08-14**

ECR # **25099** Production: X Service: X Sales: X  
Product Lines: Transportation Equipment: X Agri-vac/Pneumatic Equipment: X

### Airlock Service Specification

Walinga airlocks with adjustable tips should be checked and adjusted annually or every 100 hours of operation. The following table lists the specifications which should be maintained when performing service on Walinga airlocks.

	Tip / Casing		Rotor / End-plate	
	Set to:	Reset Spec:	Set to:	Replace Spec:
<b>1008 DT</b>	0.003	0.009	0.004	0.009
<b>1210 DT/BT</b>	0.004	0.010	0.005	0.010
<b>1314 DT/BT</b>	0.005	0.010	0.005	0.011
<b>1618 DT</b>	0.004	0.011	0.007	0.014
<b>1618 BT</b>	0.006	0.012	0.007	0.014
<b>2018 BT</b>	0.008	0.015	0.007	0.016
<b>2224 DT</b>	0.008	0.016	0.010	0.020

**NOTE:** The Tip/Casing clearance should be measured and reset on the side of the airlock opposite to the airlock tip wiper. This is necessary as the side of the airlock that has the tip wiper installed on it will typically experience normal operational wear, and using this side may result in clearances that fall below the minimum clearance and cause scraping between the Tip/Casing