

TECHNICAL BULLETIN



Subject:


Revision Of The 3510 Receiver Top

Bulletin #:	Rev:	Created by:	Date:
00-116136-0	A	JGPB	15-01-2018

ECR # **26072** Production: - Service: - Sales: X
Product Lines: Transportation Equipment: - Agri-vac/Pneumatic Equipment: X

Walinga has modified all 3510 receiver tops. The top of the 3510 has been extended in order to improve manufacturing efficiency. With this change, a filler pipe is no longer required. This pipe was installed in order to make the inlet pipe match up and fit, however it also caused some obstruction to the airflow. By extending the top an elbow has been removed from blower piping. (51-91362-6)

RECEIVER TOP, INST, 3510 (11-68171-5)



TECHNICAL BULLETIN



Subject:

Revision Of The 3510 Receiver Top

Bulletin #:

00-116136-0

Rev:

A

Created by:

JGPB

Date:

15-01-2018

ECR #

26072

Production: -

Service: -

Sales: X

Product Lines: Transportation Equipment: -

Agri-vac/Pneumatic Equipment: X

New 3510 Receiver Top



Page 2 of 2

Bulletin #: **116136**

Head Office
R.R.#5, Guelph, ON
Canada N1H 6J2
Tel (519) 824-8520
Fax (519) 824-5651

938 Glengarry Cr
Fergus, Ontario
Canada N1M 2W7
Tel (519) 787-8227
Fax (519) 787-8210

70 3rd Ave. N.E. Box 1790
Carman, Manitoba
Canada R0G 0J0
Tel (204) 745-2951
Fax (204) 745-6309

1190 Electric Ave.
Wayland, MI.
U.S.A. 49348
Tel (800) 466-1197
Fax (616) 877-3474